

SNO-KONE INSTRUCTIONS



OPERATING INSTRUCTIONS

1. Fill the hopper with ice cubes to within one inch of the top
2. Switch the motor on and wait for it to come to full speed (it takes around 60 seconds)
3. Push the handle down against the ice in the hopper with firm & even pressure

MEASUREMENTS



CLEANING INSTRUCTIONS

Wipe inside and outside of Sno-Kone machine with a cloth. Wash and dry the tray
NEVER ALLOW ANY FOREIGN OR METALLIC OBJECTS AROUND THE SHAVER