## SNO-KONE INSTRUCTIONS





## MEASUREMENTS







## OPERATING INSTRUCTIONS

- 1. Fill the hopper with ice cubes to within one inch of the top
- 2. Switch the motor on and wait for it to come to full speed (it takes around 60 seconds)
- 3. Push the handle down against the ice in the hopper with firm & even pressure

## CLEANING INSTRUCTIONS

Wipe inside and outside of Sno-Kone machine with a cloth. Wash and dry the tray
NEVER ALLOW ANY FOREIGN OR METALLIC
OBJECTS AROUND THE SHAVER